

Meyertech Ltd : Software Update Details

FusionEdit 1.24.1.0

Release Date : 1st November 2007

Program Changes in version 1.24.1.0 (1st November 2007)

Update Workstations

Fixed a problem where the operator priorities, DVR to camera mappings and DVR to matrix input mappings were not copied from the master workstation to a slave.

Program Changes in version 1.24.0.0 (30th October 2007)

DVR Mapping

Added a separate DVR site number so that the DVR can be on a different site to the cameras. Also allowed the DVR matrix input to be set to zero to prevent a remote matrix switch.

Program Changes in version 1.23.1.0 (21st August 2007)

Logon

Fixed a problem where the keyboard priority is used instead of the priority level to determine whether a user has permission to log on.

Program Changes in version 1.23.0.0 (11th October 2006)

Airlock

Checkbox to enable the new "Answer Call" button.

Program Changes in version 1.22.0.0

Alarm Plan and Site Details

Added dialog boxes to allow alarm plans and site details to be edited.

Icon X, Y Coordinates

Added editable x, y coordinate fields to various icon property dialogs.

Barrier and Door Auditing

Distinguish barriers, doors, intercoms and video-conferences from general relay auditing.

Light Aux Function Icon

Added a new aux function icon to represent a light being switched on and off.

Camera Details

Added editable location and description fields for each camera, for use with external incident reporting applications.

Monitors and Cameras

Increased the maximum number of monitors and cameras to 2048 and 4096 respectively.

Workstation Number

The workstation number is now read from the workstation licence file. The maximum number of workstations has been increased to 32.

Incident Reporting

Configure the interface to external incident reporting applications.

Mux Assisted Switches

Configure the sites and cameras that need mux input selection in order to complete video switching.

Dynamic Camera Configuring

Aux function icons can be set up to dynamically re-configure Bosch cameras when clicked.

Program Changes in version 1.21.1.0 (25th July 2006)

ANPR

Change the "T" for Town Centre to "C" for CCTV mode.

Program Changes in version 1.21.0.0

Telemetry Relay Polling

Added the option to poll a telemetry relay and update the aux function icon to match its current state.

Bosch Camera Parameter Updating

Added the option to change Bosch camera parameter values by clicking an aux function icon.

Program Changes in version 1.20.1.0

Maps Not Installed

Corrected problem where Fusion crashes during start-up if no maps are installed.

Program Changes in version 1.20.0.0

ZVR-IOM8

Extended the number of addressable relays from 24 to 32.

Map Symbols

Corrected problem where map symbols (cameras, presets, etc.) are sometimes not redrawn.

Program Changes in version 1.19.2.0

Extended Fusion Audit User Synchronisation

Extended the user synchronisation from Fusion Audit to support internal actions and actions from legacy keyboards.

Keyboard Priority

Corrected problem where keyboard priority was allowed to take illegal values greater than 9.

Program Changes in version 1.19.1.0

Configurable Monitor Buttons

Made the file "MonitorButton.dat" holding the monitor button details optional.

Program Changes in version 1.19.0.0

Configurable Monitor Buttons

Added 8 new configurable monitor buttons accessible via the "copy monitor" button. The default mode of the buttons can be selected, together with the monitor number and description for each button.

Program Changes in version 1.18.1.0

Secure User Logoff

Fix made to ensure that once an operator has logged off from FusionEdit no editing capabilities are accessible for the user.

Resource Leak

Fixed resource leak that caused the icon cursor to disappear after a few minutes use.

Program Changes in version 1.18.0.0

Auxiliary Function Buttons Extended

Added an extra button to the Fusion maps that allows for the configuration of a video conferencing button. This video conferencing button can be configured to switch cameras to monitors and trigger relays.

Program Changes in version 1.17.0.0

Master Workstation Control

The master workstation control has been extended to support the deletion of log files that are created by Fusion. This is a feature for customers who do not utilise FusionAudit. If FusionAudit is used on the system then the files will be trimmed automatically.

