

Meyertech Ltd : Software Update Details

Mpower 2.37.0.0

Release Date : 23rd May 2011

Program Changes in version 2.37.0.0 (23rd May 2011)

ZSC-250-IS

New ZSC-250-IS unit supported.

ZSC-1000plus/1000/500

New 'Polled' option for the 'Remote Station' on the 'Intersite Port' tab.

Program Changes in version 2.36.0.0

ZSC-1000plus/1000/500

New enables available.

ZVS-MSI

New protocols available.

Program Changes in version 2.35.0.0 (11th June 2010)

ZSC-1000

Allow pan, zoom, tilt and focus directions to be reversed.

Program Changes in version 2.34.0.0 (28th August 2009)

All ZVS and ZSC

Fixed problem reading the serial number.

ZVS-MSI

Added configuration support for remote matrixes via TTX309 or Tx-Control interface (bespoke version)
Added support for Advanced Fire Alarm System

ZSC-1000

Fixed problem saving baud rate on ZVM port tab.
Added description of 'Through Routing (e.g. TVNP)' on site routing tab.

Program Changes in version 2.33.3.0 (10th October 2008)

ZSC-1000

Fixed problem saving, loading, uploading and downloading event zero and alarm zero.

Program Changes in version 2.33.2.0 (29th September 2008)

ZVS-ROM-16

Fixed problem showing incorrect baud rate values.

Program Changes in version 2.33.1.0 (16th September 2008)

ZSC-1000

Increased theoretically possible input and output sizes of matrixes to 65536. Fixed invalid mapping ranges problem.

Program Changes in version 2.32.0.0 (5th September 2008)

ZVS-ROM-16

Added configuration support.

Program Changes in version 2.31.2.0 (16th July 2008)

ZSC-500

Fixed problem causing the camera mapping tab to appear blank.

Program Changes in version 2.31.1.0 (14th July 2008)

Sequence Camera Number

Fixed problem restricting sequence camera number to 256.

ZSC Site Controller

Removed SSWT CCTV protocol from Matrix page.

Program Changes in version 2.31.0.0 (7th July 2008)

ZVS-MSI

Added Pelco-D protocol and Sanyo DVR.

ZSC Site Controller

Added Pelco-D and SSWT CCTV protocols, together with a Pelco extended address range enable switch.

Specific Site Data Subdirectories

Fixed a problem that was generating a run-time error when creating the initial ZSC-1000 and site subdirectories.

Program Changes in version 2.30.0.0 (10th May 2008)

Camera Mapping

Increased number of camera maps to 256.

Program Changes in version 2.29.1.0 (4th March 2008)

Alarm Events

Fixed problem assigning events above 255 to alarms.

Program Changes in version 2.29.0.0 (20th February 2008)

Alarms and Alarm Monitors

Added group numbers.

ZVS-MSI

Added Tecton DVR and Cobyt controller.

Matrices

Added Virtual Matrix Manager.

Intersite Port

Fixed problem downloading intersite port settings for config versions 27, 107 and 507.

Program Changes in version 2.28.0.0 (22nd October 2007)

Camera Mapping and Alarm Events

Modified to include different operating modes.

ZVR-530

Modified save and load for additional presets.

Program Changes in version 2.27.0.0 (Internal)

Intersite

Added priority and turnaround.

Program Changes in version 2.26.2.0 (22nd May 2007)

Import Operators

Fixed a problem importing the operators list from newer versions of Fusion.

Program Changes in version 2.26.1.0 (24th April 2007)

Logger.dll

Fixed a start-up problem where Mpower reports that it can't find the logger.dll.

Program Changes in version 2.26.0.0 (16th March 2007)

JVC Camera

Fixed a problem saving and loading backups.

Site Controller PC Port 1

Added parity setting and spot monitor to station number mapping.

ZVR-130 and 530

Added caption control and extra OSD setup to backup and restore functions.

Program Changes in version 2.25.1.0 (31st October 2006)

ZSC-1000plus

Fixed a problem causing the ZSC-1000plus Series 2 OSD page to appear blank for configuration version 109.

Program Changes in version 2.25.0.0 (18th October 2006)

Command Line

Support for the serial port number to be passed as a command line parameter. The command line will take the form of /port:X.

Program Changes in version 2.24.4.0 (17th October 2006)

ZSC-500

Includes previously omitted support for configuration version 507.

Program Changes in version 2.24.3.0 (11th October 2006)

ZSC-1000plus

Displays key field for bespoke configuration version 110.

Program Changes in version 2.24.2.0 (6th October 2006)

Series 3 Matrix

Supports configuration version 3. Added ranges and defaults to OSD screens and 16 lines instead of 11.

Program Changes in version 2.24.0.0 (16th June 2006)

Series 2 OSD

Added support for the new Series 2 OSD configuration method.

Monitor Blanking Timeout

Added a bespoke monitor blanking timeout for configuration version 110.

Program Changes in version 2.23.0.0

Covert Site

Further bespoke covert site additions for configuration versions 28, 108 and 508.

Unknown Configuration Versions

Added a warning message to be displayed if the configuration version received from the unit does not match any of those handled by this version of Mpower.

Program Changes in version 2.22.1.0**ZVS-MSI-48**

Corrected problem configuring ZVS-MSI-48 version 1 matrix and configuration enable parameters.

Program Changes in version 2.22.0.0**ZSC-1000plus, 500 and 1000**

Additional enable flags for legacy MUX and VCR protocols.

ZSC-250 and 1000plus for Intersite

Additional intersite mode selection and site setup.

ZVS-MSI-xx

Added Plettac receiver to the available peripheral configuration types.

Program Changes in version 2.21.0.0**ZVK-77**

Support for backup and restore of left handed user mode settings..

Covert Site

Bespoke covert site additions for configuration versions 26 and 506.

ZVS3-VRM

Corrected problem where, under certain circumstances, the configuration dialog for the ZVS3-VRM becomes unavailable.

Program Changes in version 2.20.1.0**Serial Numbers**

Added serial number support for the ZSC-1000plus, ZSC-1000, ZSC-500, ZSC-250, ZVS-MSI-xxx, ZSC-250-IP and ZVS-MSI-IP.

ZVS-MSI

Added Panasonic 200 and Baxall Mux to the list of supported peripherals.

ZVS-MSI-IP

Added Neurodynamics protocol to the peripheral list.

Program Changes in version 2.20.0.0**Audit Mode**

Support for Audit mode on PC2 Port of ZSC-1000plus, ZSC-1000 and ZSC-500.

ZVK-77

Support for ZVK-77 User Logins, includes import from Fusion operator files.

Program Changes in version 2.19.2.0**ZoneVu Communications**

Corrected problem where Mpower sometimes crashed when there was a high volume of traffic on the ZoneVu network.

Program Changes in version 2.19.1.0**IP Communications**

Corrected problem where Mpower would crash when communicating with a site controller over IP.

Program Changes in version 2.19.0.0

LAN Speed

Support ZSC-250-IP and ZVS-MSI-IP LAN speeds.

Program Changes in version 2.18.0.0**ZVK-77**

Support for ZVK-77 complete backup and restore.

Program Changes in version 2.17.0.0**Series 3 OSD Matrix**

Limited the monitor offset value to multiples of 128, extended the monitor caption range to 2048 and added a new ZoneVu Port tab.

Series 3 Duplex Matrix

Added Series 3 Duplex matrix type selection for site controllers ZSC-1000plus, ZSC-1000 and ZSC-500.

Program Changes in version 2.16.0.0**Bosch Camera**

Support for Bosch camera backup, restore and menu control.

ZVS3-OSD

New ZVS3-OSD Diagnostics utility.

ZVS3-VRM

New ZVS3-VRM configuration screens.

Program Changes in version 2.15.2.0**Neurodynamics**

Added Neurodynamics protocol to ZVS-MSI-IP peripheral list.

360 Vision Dome

Added 360 Vision Dome to MSI-Mxx peripheral list.

Program Changes in version 2.15.1.0**Confirm Download**

Added "Confirm Download" dialog box to all existing dialogs.

Resource Usage

Solved 100% resource usage problems.

ZVR-530

Updated support for ZVR-530.

JVC Camera

Support for JVC cameras store scene.

Program Changes in version 2.14.0.0**ZVS-MSI**

Updated support for ZVS-MSI and added parity setting to PC Ports tab.

ZSC-250

Updated support for ZSC-250.

Engineering Mode

Added engineering mode to allow partitioning of advanced settings.

Program Changes in version 2.13.0.0

New Products

Added support for new products – ZVS-MSI-IP and ZSI-330.

