

## Meyertech Ltd : Software Update Details

### Mpower 2.31.1.0

Release Date : 14<sup>th</sup> July 2008

---

#### Program Changes in version 2.31.1.0 (14<sup>th</sup> July 2008)

**Sequence Camera Number**

Fixed problem restricting sequence camera number to 256.

**ZSC Site Controller**

Removed SSWT CCTV protocol from Matrix page.

---

#### Program Changes in version 2.31.0.0 (7<sup>th</sup> July 2008)

**ZVS-MSI**

Added Pelco-D protocol and Sanyo DVR.

**ZSC Site Controller**

Added Pelco-D and SSWT CCTV protocols, together with a Pelco extended address range enable switch.

**Specific Site Data Subdirectories**

Fixed a problem that was generating a run-time error when creating the initial ZSC-1000 and site subdirectories.

---

#### Program Changes in version 2.30.0.0 (10<sup>th</sup> May 2008)

**Camera Mapping**

Increased number of camera maps to 256.

---

#### Program Changes in version 2.29.1.0 (4<sup>th</sup> March 2008)

**Alarm Events**

Fixed problem assigning events above 255 to alarms.

---

#### Program Changes in version 2.29.0.0 (20<sup>th</sup> February 2008)

**Alarms and Alarm Monitors**

Added group numbers.

**ZVS-MSI**

Added Tecton DVR and Cobyt controller.

**Matrices**

Added Virtual Matrix Manager.

**Intersite Port**

Fixed problem downloading intersite port settings for config versions 27, 107 and 507.

---

#### Program Changes in version 2.28.0.0 (22<sup>nd</sup> October 2007)

**Camera Mapping and Alarm Events**

Modified to include different operating modes.

**ZVR-530**

Modified save and load for additional presets.

---

#### Program Changes in version 2.27.0.0 (Internal)

**Intersite**

Added priority and turnaround.

---

## Program Changes in version 2.26.2.0 (22<sup>nd</sup> May 2007)

### Import Operators

Fixed a problem importing the operators list from newer versions of Fusion.

---

## Program Changes in version 2.26.1.0 (24<sup>th</sup> April 2007)

### Logger.dll

Fixed a start-up problem where Mpower reports that it can't find the logger.dll.

---

## Program Changes in version 2.26.0.0 (16<sup>th</sup> March 2007)

### JVC Camera

Fixed a problem saving and loading backups.

### Site Controller PC Port 1

Added parity setting and spot monitor to station number mapping.

### ZVR-130 and 530

Added caption control and extra OSD setup to backup and restore functions.

---

## Program Changes in version 2.25.1.0 (31<sup>st</sup> October 2006)

### ZSC-1000plus

Fixed a problem causing the ZSC-1000plus Series 2 OSD page to appear blank for configuration version 109.

---

## Program Changes in version 2.25.0.0 (18<sup>th</sup> October 2006)

### Command Line

Support for the serial port number to be passed as a command line parameter. The command line will take the form of /port:X.

---

## Program Changes in version 2.24.4.0 (17<sup>th</sup> October 2006)

### ZSC-500

Includes previously omitted support for configuration version 507.

---

## Program Changes in version 2.24.3.0 (11<sup>th</sup> October 2006)

### ZSC-1000plus

Displays key field for bespoke configuration version 110.

---

## Program Changes in version 2.24.2.0 (6<sup>th</sup> October 2006)

### Series 3 Matrix

Supports configuration version 3. Added ranges and defaults to OSD screens and 16 lines instead of 11.

---

## Program Changes in version 2.24.0.0 (16<sup>th</sup> June 2006)

### Series 2 OSD

Added support for the new Series 2 OSD configuration method.

### Monitor Blanking Timeout

Added a bespoke monitor blanking timeout for configuration version 110.

---

## Program Changes in version 2.23.0.0

### Covert Site

Further bespoke covert site additions for configuration versions 28, 108 and 508.

**Unknown Configuration Versions**

Added a warning message to be displayed if the configuration version received from the unit does not match any of those handled by this version of Mpower.

---

**Program Changes in version 2.22.1.0****ZVS-MSI-48**

Corrected problem configuring ZVS-MSI-48 version 1 matrix and configuration enable parameters.

---

**Program Changes in version 2.22.0.0****ZSC-1000plus, 500 and 1000**

Additional enable flags for legacy MUX and VCR protocols.

**ZSC-250 and 1000plus for Intersite**

Additional intersite mode selection and site setup.

**ZVS-MSI-xx**

Added Plettac receiver to the available peripheral configuration types.

---

**Program Changes in version 2.21.0.0****ZVK-77**

Support for backup and restore of left handed user mode settings..

**Covert Site**

Bespoke covert site additions for configuration versions 26 and 506.

**ZVS3-VRM**

Corrected problem where, under certain circumstances, the configuration dialog for the ZVS3-VRM becomes unavailable.

---

**Program Changes in version 2.20.1.0****Serial Numbers**

Added serial number support for the ZSC-1000plus, ZSC-1000, ZSC-500, ZSC-250, ZVS-MSI-xxx, ZSC-250-IP and ZVS-MSI-IP.

**ZVS-MSI**

Added Panasonic 200 and Baxall Mux to the list of supported peripherals.

**ZVS-MSI-IP**

Added Neurodynamics protocol to the peripheral list.

---

**Program Changes in version 2.20.0.0****Audit Mode**

Support for Audit mode on PC2 Port of ZSC-1000plus, ZSC-1000 and ZSC-500.

**ZVK-77**

Support for ZVK-77 User Logins, includes import from Fusion operator files.

---

**Program Changes in version 2.19.2.0****ZoneVu Communications**

Corrected problem where Mpower sometimes crashed when there was a high volume of traffic on the ZoneVu network.

---

**Program Changes in version 2.19.1.0****IP Communications**

Corrected problem where Mpower would crash when communicating with a site controller over IP.

## Program Changes in version 2.19.0.0

### LAN Speed

Support ZSC-250-IP and ZVS-MSI-IP LAN speeds.

---

## Program Changes in version 2.18.0.0

### ZVK-77

Support for ZVK-77 complete backup and restore.

---

## Program Changes in version 2.17.0.0

### Series 3 OSD Matrix

Limited the monitor offset value to multiples of 128, extended the monitor caption range to 2048 and added a new ZoneVu Port tab.

### Series 3 Duplex Matrix

Added Series 3 Duplex matrix type selection for site controllers ZSC-1000plus, ZSC-1000 and ZSC-500.

---

## Program Changes in version 2.16.0.0

### Bosch Camera

Support for Bosch camera backup, restore and menu control.

### ZVS3-OSD

New ZVS3-OSD Diagnostics utility.

### ZVS3-VRM

New ZVS3-VRM configuration screens.

---

## Program Changes in version 2.15.2.0

### Neurodynamics

Added Neurodynamics protocol to ZVS-MSI-IP peripheral list.

### 360 Vision Dome

Added 360 Vision Dome to MSI-Mxx peripheral list.

---

## Program Changes in version 2.15.1.0

### Confirm Download

Added "Confirm Download" dialog box to all existing dialogs.

### Resource Usage

Solved 100% resource usage problems.

### ZVR-530

Updated support for ZVR-530.

### JVC Camera

Support for JVC cameras store scene.

---

## Program Changes in version 2.14.0.0

### ZVS-MSI

Updated support for ZVS-MSI and added parity setting to PC Ports tab.

### ZSC-250

Updated support for ZSC-250.

### Engineering Mode

Added engineering mode to allow partitioning of advanced settings.

---

## Program Changes in version 2.13.0.0

### New Products

Added support for new products – ZVS-MSI-IP and ZSI-330.

---

